

LEHMON: SUNDERLAND 4093 (2 LINES).

communications to be addressed to  
THE SURVEYORS.

Reference

S.

063458-003455-0254

# Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 16th August, 1943.

Dear Sir,

"EMPIRE ALLIANCE". Sunderland Report No. 33738.

With reference to your Classing Letter of the 13th instant in respect of the above vessel we enclose herewith as requested a sketch showing the position of the Water Ballast Tank in the Engine Room Double Bottom.

We have to state that the spacing of the transverses in way of the cargo oil tanks is 8' 11" and 7' 2" and not 8' 11" and 8' 0 $\frac{1}{2}$ " as reported.

We are, Dear Sir,  
Yours faithfully,  
THE SURVEYORS,  
PER: *W. C. Muller*

The Secretary,  
WOKINGHAM.

H

R

17 AUG 1945

The Surveyors should be requested to indicate on their first Embay Reports, in future similar cases, the length of the double bottom in accordance with Circular 1284. J.C.D. 6/11/45.



© 2020

Lloyd's Register  
Foundation