

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "MAUDIE"

Report G.R.

No. 17706

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

When due

2 100 A.1. (steel)

2 Dks (steel)

Cell DB 331' 995t. Dta 30' 780t. APT 20t.

FK. Intermediate Tween deck bulkhead in after hold dispensed with — 5' BH to upper DK. 1BH to 2nd Dk. only. Conn. Lloyd's A.C.P. P39, B115, F45.



M. A.S.
16-9-20

It is understood the ribs in edges of butts of strake below sheerstrake, deck of bridge, are spaced as required, but the Surveyors should be requested to state if this is so.

© 2020
Lloyd's Register
Foundation

003474-003478-0182