



# Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.

ROTTERDAM, 10th September, 1959.

Westersingel 106, P.O. Box 701

reference:

L.(S)

Dear Sir,

"HYALINA", Rotterdam Report No. 47784.

In reply to your classing letter of the 4th instant, concerning the above, we beg to state that when examining the seaconnections we found the stated valves eroded (graphited) in many places and especially near flanges of covers, while the portside overboard discharge of main condenser was wasted through in the neck of flange and has been temporarily plugged.

We trust the above is the information required, and remain,

Yours faithfully,

The Secretary,  
LONDON.

RECEIVED

14 SEP

x 8p3



© 2020

Lloyd's Register  
Foundation

003479-003486-0183



ER

CLASSIFICATION

14

mm

Noted

Sub

15/9/59



© 2020

Lloyd's Register  
Foundation