

COPY.

25th January 1935.

Dear Dr. Webster,

In looking over the First Entry Report on the "ANTEO" a little point has arisen which I shall be glad if you can clear up before submitting the case to the Classification Committee, as this would be preferable to making a conclusion in the classing letter.

The riveting of butts of the side shell plating is shown as treble riveted, strapped and lapped. The treble riveting is in accordance with the approved plans, but the spacing of the 22 mm. diameter rivets is given as 88 mm., which of course, as you know, should be 77 mm. unless these butts are double strapped.

With kind regards,

and hoping you have enjoyed your trip to Italy,

G. Webster, Esq., D.Sc.

GINCK.

Blaslow.



© 2020

Lloyd's Register
Foundation

003487-003494-0058