

17 - AUG 1956

Rpt. C. 11 (Cont)

COPY

Index No. \_\_\_\_\_  
(For London Office use)

29-55-506

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "PRECILA" Official No. 180077

Port of Registry Panama

This ship has been under survey at Hong Kong,  
on 17th July, 1956 and the following alterations to the conditions of

assignment of loadlines have now been effected/found:—

Port & starbd side coaling hatches (fwd) now removed, and deck openings  
blanked off with steel plates.

Two 24" ventilators abreast No.3 hatchway removed, and deck openings blanked  
off with steel plates.

*J.L.V. Whittle*

J.L.V. Whittle

Surveyor to Lloyd's Register.

HONG KONG.

18th July, 1956.

*Noted  
JMB  
10-9-56*

A copy of this Report has been placed on board.

A copy of this Report has been sent to New York Office.

2m.7.54. T.



© 2020

Lloyd's Register  
Foundation

003495-003502-0213