

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name PRECILA

Official No. \_\_\_\_\_

Port of Registry PANAMAThis ship has been under survey at SASEBO, JAPAN

on July - August 1955 and the following alterations to the conditions of assignment of loadlines have now been effected/found:—

Annual Freeboard Survey held & markings verified:

2 upper deck plates renewed.  
1 stinger plate failed.  
Doublings & reinforcement fitted at Nos 3 & 7 hatches.  
80 hatch covers renewed.  
Repair & renewals effected to casing top, skylights, sidelights, bulwarks, air pipes, vents, & scuppers.

Alterations:

① Additional strengthening carried out for increased draught.  
Tonnage hatch plated over. Scuppers & freeing ports in Tonnage well permanently closed.  
Arrangements made for rigging lifelines.  
Amended freeboards, authorized by Secretary's cable 4.8.55, have been cut in & verified.

② Deep tank forward converted to dry-cargo hold. Alterations carried out in accordance with plan of conversion which is stated to have been approved 10.3.53. Hatchweb has been added to support wood covers closing the new hatchway.

[From Shimonoeki Rpt 8 No 480 - 8. August. 1955]

14/2 = 3 FEB 1956

A copy of this Report has been placed on board.



© 2020

Lloyd's Register  
Foundation