

ACTION is DEFERRED for Repairs.

Surveyors.....

Received from Chief Surveyors.....

NAME "TRANSMARS"

REPORT Bos.

No. 4877

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Temporary repairs to leakage. ~~When due~~

N O T E D.

Subject to poop sheerstrake etc. (s.s.) being specially examined and dealt with as necessary also to leaky shell rivets in E.R. and pump room being renewed at the next drydocking, and to buckled fore deck gangway plating being further examined on completion of present contemplated voyage from New York to Aruba.

ABM.
2.2.59.



© 2020

Lloyd's Register
Foundation

003503-003512-0108