

13 OCT 1961

Received from Chief Ship Surveyor.....

NAME "BHARATRAJA" REPORT CAL. No. 20357

standing Conditions of Class: SUBJECT to corrugated side shell plating (p & s) being specially examined and to sheerstrake plates Nos.1 & 2 in 1st below sheer and No.1 contour plate etc. (p.s.) being specially examined and dealt with as necessary next drydocking, also to bulkhead between Nos.4 & 5 holds (part doubled) being dealt with as necessary at the Special Survey.

ACTION is DEFERRED for examination in drydock after grounding and fire damage.

Appendix. (As before ~~or None~~)

ays due: SPECIAL SURVEY (C) due 7,61.--Postponement until 10,61 approved without a General Examination being held.

ce of Present Survey: (Afloat ~~and in drydock~~)

Equipment:- Wear and tear repairs.  
Bower anchor lost - spare bower fitted.

ial Features:

interim Certificate in order (Yes ~~No~~ ~~None~~)

s Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: 10,61.

mmendation:

SUBJECT as above and to a bower anchor being supplied at the earliest opportunity, but further ACTION be DEFERRED for Special Survey by 10,61 and for examination in dry dock after grounding also for fire damage.

SUBJECT.

IN S.R.L.  
Drydocking (grounding and fire).

IN S.R.L. APPENDIX.  
Stem plate in 1st below sheerstrake (p.s) indented.

NOTE:- The Surveyors report the ship would discharge her present cargo at ports on the West coast of India and then proceed to Bombay where she is to be broken up.