

4E


subject to the evaporator not being used until repaired.

19 MAY 1960

Received from Chief Engineer Surveyor.....  
d by Chief Engineer Surveyor.....  
S NAME "BHARATRAJA" REPORT CAL No. 19480.

The Surveyor reports some repairs effected to the securing arrangements of the HP valve liner and recommends that class be made subject to the HP valve liner being specially examined at the next engine survey (due 7.61).

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended *and as above*



© 2020

Lloyd's Register  
Foundation



003503-003512-0171

17.5.60.