

WRECK

SECTION

No. 725

Wreck Report No.

REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 25809 in R.B. Wreck Book, p. 171/59

Date of writing this report 16th December, 19 59.

Ship's Name s.s. "PICTON" of Pt. Colborne Tons { Gross 1895

Net 1184

Built at Middlesbrough When 1929 3 Casualty notice sent to Owner --- Owner's reply ---

Owners ---

Managers ---

Address ---

WRECK

SECTION

No. 725

Classification details

BS*	MBS* 4,55
Great Lakes & Limited	BS M 2,59
Self of St. Lawrence	sp 2,57
Service	
11,57	ts 11,57 CL
ss Lake 11,57	
A.S. 4,59	

Casualty November 1959

Casualty

This ship is in port at Cristobal, Panama, with extensive damage sustained while being towed from the Great Lakes to Vancouver.

SOURCE OF INFORMATION

PICTON.—Vancouver, Nov. 10.—Steamer Picton, one of two steamers being towed here, for conversion into barges, by tug N. R. LANG, has been left at Cristobal because of damage sustained during a hurricane. Steamers Picton and DAVID BARCLAY were taken in tow at Lauzon by the N. R. LANG, which was forced to heave to for four days at the Bahamas in a hurricane. The ships were two of 12 recently purchased by the Powell River Company, Ltd., for conversion into fuel barges. The N. R. LANG is towing the DAVID BARCLAY up the Pacific coast.—New York Maritime Association. (See issue of Nov. 9.)

Record " IN PORT DAMAGED 11,59"

Committee FRIDAY 18 DEC 1959

Committee's Minute

1m, 11,58

Note Yes

(She)

003525-003532-0122

Noted for Header

FRIDAY 20 MAY 1960

Non-Confidential

Note Yes

© 2020

Noyes's Register

GENERAL COMMITTEE

Thursday,
16th June, 1960.
Classing Committee,
decision confirmed.

A.B.L.



© 2020

Lloyd's Register
Foundation