

2 - thickness 25.5 mm ✓ Are the shell plates welded or flanged

Engine No. 2578 Made by A.B. Lucholmen Motala
Boiler No. 2579
For One Sundsvärket No 42

See Report No. 10788

It is submitted that a copy of this Report be
forwarded to the ~~returned~~ Surveyors for their
guidance and for completion.

Date

21. 7. 36

Im, 6, 36.

Copy Rpt
Sent Hbg
5/8/36

003525-003532-0167

ensile strength As per Rule Thickness: Sides 16 mm Back 16 mm Top 16 mm

Mr Coote



© 2020

Lloyd's Register
Foundation

Are the approved plans of boiler and superheater forwarded herewith
(If not state date of approval.)

20-11-20