

1m.10.33.

F.E.

fees paid

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw Ketch "REIGHTON WYKE" Rpt. Hul. No. 47562

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2407

Depth "d" --

2nd Long. No. 6741

Proportions = $\frac{L}{D}$ --

Framing Angle frames as approved

Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 'Steam Trawler'

1 Dk.

BK 7½", 4 BH, Cem., Lloyd's A & CP.

Q 86', F 25'.



[Signature]
4.2.37

[Signature]



© 2020

Lloyd's Register
Foundation

003525-003532-0185

Mr Loder To follow
Have you the
dynamometer sheets
Roll
5/2



© 2020

Lloyd's Register
Foundation