


Wetherall has been advised by phone.  
rding requirement for spare napeller  
It & agrees that such spare should  
carried on board & the order for necessary  
es will be made

Stressed however that supply position  
ery bad & it may be a considerable  
before the requirement can be met. X  
all ships



© 2021

Lloyd's Register  
Foundation

003534-003540-0078