



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

3rd Floor, 25 Ballindamm, Hamburg, 1

Telegrams: Surveyors, Hamburg

Telephone: No. ~~00330~~

33 35 39

RECEIVED

8 AUG 1950

5th August, 1950.

Reference

28/50

Dear Sir,

S.S. "LACKLAN".

With reference to your Classing Letter of the 1st inst. relative to the above vessel, we have to state that the Surveyor's stamp could not be identified on the new boiler furnaces.


Further, the new Owners state that they do not hold copies of the test certificates covering the furnace nor were they on board the vessel.

We are, Dear Sir,

Yours faithfully,

The Secretary,
London.

For the Surveyors.



Lloyd's Register
Foundation

003534-003540-0143

E

Referred to Mr. Perris:

LKP

It is submitted the Hamburg manager be
asked to make enquiries regarding the origin of
the new fumes now fitted on whether they
ordered to the Society's specification or not.

May 9/81 or



© 2021

Lloyd's Register
Foundation