

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

2 JAN 1958 **4E**

NAME.....OMALA.....REPORT.....Rot.....No...46436

DBS due 8.58 now held.

Docking, screwshaft seen.

C.S. Advanced.

Repairs.

IT IS SUBMITTED that this vessel is eligible
for the record DBS 10.58 and TS (CL) 10.58.

S.R.L. - Appendix ^{States} Spare screwshaft to be examined
after 12 months service, if and when fitted.



© 2021

Lloyd's Register
Foundation

22.12.58.

003531-003540-0213