

26 SEP 1962

Ship's name "JALAKANXA"Port CAL.No. 20871Last survey date 29.8.62.

Class is subject to indented shell plate No.4 etc. in 2nd below sheer (p.s.f) and to indented plating in 'E' & 'F' strakes frs.52-53 (ps) being examined and dealt with as necessary next drydocking, and to set up keel and bottom shell plating (p & s) being specially examined and dealt with as necessary, also to indented shell plate F.4 (s.s.f) being dealt with by the S.S., and to 15 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)Nature of present survey (afloat ~~XXXXXXXXXXXXXXXXXX~~)

Equipment: Loss of 4 lengths of chain cable and bower anchor.  
Supply and verification of 4 lengths of chain cable.

Recommendation

SUBMITTED the ship is eligible to remain as classed, subject as above and to a bower anchor being supplied at the earliest opportunity.

As Now Subject.

IN S.R.L. APPENDIX

Indented No. 4 shell plate  
in 2nd below sheer (s.s.f).  
Shell plate D.2 (s.s.f) indented.

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded that they have satisfied themselves that the chain cables now fitted ride satisfactorily over the cable lifters.

U.S.S. Records Dept.  
to note.

Lloyd's Register  
Foundation