

COPY

LLOYD'S REGISTER OF SHIPPING



Port LIVERPOOL.

12th February, 1957.

This is to Certify that I have

Surveyed the S.S. "TANLAN" 293 Tons gross of Liverpool on the

22.1.57 and subsequently whilst in No.1 Birkenhead Drydock and

in West Float Dock on account of docking, annual freeboard survey and damage stated to have been sustained by ranging alongside quay at Carrickfergus on the 30.12.56,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all/repairs recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as now classed

in the Register Book with fresh record of docking 1,57 subject to indented No. 5 shellplate psa in main sheer, etc., being examined and dealt with as necessary at next Special Survey and to 1 length of chain cable being supplied at earliest opportunity and as previously recommended.

being fit to carry her usual cargoes.

Surveyor to Lloyd's Register
(J.A. CHEYNE).

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

