




Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,

Donegall Square, West,

Belfast, 20th April 1927



The Secretary
London

Dear Sir

Belfast Report No. 9721 "Pat Freemantle"

Alternate groups of lamps in the engine room are supplied from lighting circuits so arranged that the fusing of any cut-out (other than a cut-out at the main switchboard) will not leave the spaces in darkness.

I regret that this was omitted from my report.

Yours faithfully
R. Lee Amies.



© 2020

Lloyd's Register
Foundation

003549-003555-0133

Lamp, switch & Fuse on each pole

Referred to the Chief Engineer Surgeon.

Wm,

Also for Mr. S. A. Hill to note.

2 MAY 1927

PS
5/5/27



© 2020

Lloyd's Register
Foundation