

Gross Tonnage

374.67

Depth of beam at side of uppermost continuous deck. See Sec. 3 (1c)

D. 14'-0"

Owners The Yorkshire Ste...

5c, 9, 30.

Robert Hewett

5

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se " BEACHFLOWER* Rpt. *Hul* No. *41464*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92).

1st Lang

Transverse No. *2100*

Depth "d" */*

Framing: Table No. */*

Description *Sub angle frames as approved*

Longitudinal No. *5906*

Proportions Length
Depth =

Deck Sheerstrake

as approved



Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. 1. (Steel) Steam Hawler.
1 D^K
B.K 7 1/2", H.B.H, Cem, Lloyds A R.P.
Q 81', F 24'.



© 2020

Lloyd's Register Foundation

003556-003566-0028

DOUBLE BOTTOM. Angle ... Poop Deck, Angle, C or T ...