

Received from Chief Ship Surveyor

119 MAY 1959

SHIP'S NAME "PEGASI"

REPORT

Sws.

No. 26475

VC

Standing Conditions of Class: None.



Improvement of Certificate (~~XXXXXXXXXX~~ As before or None)

Where of Present Survey: (~~XXXXXXXXXX~~ Afloat and in dry dock)

Docking; Permanent/deferred W & T. repairs; E.W. repairs to stern frame rudder post (fractured); Eqt- renewal and verification of one lugless joining shackle.

Recommendation: SUBMITTED record of 'DS. 4.59' be assigned, SUBJECT to indented No.3 keel plate being specially examined and dealt with as necessary, and stern frame rudder post (E.W. 4.59) being specially examined, next drydocking.

DS. 4.59. SUBJECT.



Lloyd's Register  
Foundation

Blk(new)

003556-003556-0162