



RECEIVED

17 May 1957

# LLOYD'S REGISTER OF SHIPPING

Lloyds Bank Chambers,

Albert Road, Middlesbrough

Telephone: Middlesbro' 43431-2

16th. May 1957.

Dear Sir,

## "ORO" Report No. 20957.

With reference to your classing letter dated 14th. May, we have to state that the buckled stem and stem plating were not dealt with at this time and a new interim certificate has consequently been issued, a copy of which is forwarded herewith.

Yours faithfully,  
The Surveyors,

per:-

The Secretary,  
LONDON.

Encl.



© 2021

Lloyd's Register  
Foundation

003567-003571-0244



CLASSIFICATION

10m

R.A.J.

H

Ly 12/5/54

THE SHIPPER

copy of which is forwarded herewith.  
new interline conflict with a consequence of a request in  
at the present time, it is not clear what the shipping line  
the present time, it is not clear what the shipping line  
the present time, it is not clear what the shipping line

"CRO" Report No. 5021

1954. 1954. 1954.

Alfred King, Widdicombs  
Floyd Bank Chambers

ROADS REGISTER OF SHIPPING



© 2021

Lloyd's Register  
Foundation