

14th May, 1957.

MIDDLESBROUGH

0959 - As recommended.

0957 "ORO" As recommended. It is concluded that the repairs to buckled stem and stem plating previously recommended to be dealt with at the Special Survey are still outstanding and, if so, an amended Interim Certificate should be issued.



© 2021

Lloyd's Register  
Foundation

003567-003571-0245