

Received from Chief Ship Surveyor

9 MAY 1957

NAME

"O R O"

REPORT

Mdb.

No. 20957

standing Conditions of Class:

Subject to buckled stem and stem  
plating being dealt with at the Special Survey.

sement of Class (B) (~~As before~~ or None)

e of Present Survey: (Afloat ~~and in dry dock~~)

Repairs on account of damage due to contact with other ship.

Recommendation:

SUBJECT as above.

*DD*  
8.5.57

As Now. Subject.

IT IS FURTHER SUBMITTED the Surveyors be informed  
it is concluded that the repairs to buckled stem and stem plating,  
previously recommended to be dealt with at the Special Survey,  
are still outstanding, and if this is confirmed an amended Interim  
Certificate should be issued.



© 2021

Lloyd's Register  
Foundation