

20 NOV 1958

NAME "LEPTON"  
AR.REPORT a) Cco.  
b) Rot.No. 5504.  
46292.

inding Conditions of Class: Subject to permanent repairs to indented side shell plating etc. (p.s) in way of No.7 wing tank at the next docking and to indented poop sheerstrake plating etc. (p.s) at the Special Survey.

ement of Certificate (As before ~~XXXXXX~~)


of Present Survey: (Afloat and in dry dock)

- a) Docking and examination on account of grounding damage.
- b) Further docking on account of grounding.

ondation: SUBMITTED record of 'DS 10,58' be assigned as recommended SUBJECT as above and to set up bottom shell plating etc. (p & s) being specially examined and dealt with as found necessary next drydocking and before being recommissioned. This ship is to be laid up in the River Blackwater for an indefinite period.  
DS 10,58. Subject.

S.R.L. APPENDIX.

(Pitting of bottom plating internally in Nos. 4, 5, 6 & 8 centre and No.5 (s.s) tanks to be kept under observation).



© 2021

Lloyd's Register  
Foundation

*James*  
17/11/58