

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME

"LAIRDSHILL"

REPORT

G/s.

No. 85569

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Nature of Survey

Docking - Wat repairs

When due

Subject to rudder post of stern frame (E.W. & reinforced (6, 56)
being specially examined next dry docking.



© 2021

Lloyd's Register
Foundation