

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "LADY DENISON-PENDER" report Gls. No. 40414
For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____



* 100 A.1. (steel) "Shelter Dk. with freeboard.
2 Dks. (upper str.-w.s) & Shelter Dk (pt. str.-beaks.)

Cell DBa 54', uE 23', f 119'. 271 t. FBT

4 BH to Shelter Dk 1 BH to upper Dk.

FK. ~~200~~ 1. pt. com. Lloyd's A.C.P. B on Shelter Dk 84'.

M *AES*
12-10-20

L. G. S.
8/12/20

It is concluded a hand pump is fitted to fore peak tank top as shown on approved pumping plan, but the surveyors should be requested to state if this is so.

003581-003590-0232

Lloyd's Register
Foundation