

Royt

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St Se " PORT ALFRED Rpt. Indb No. 14103

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

1st Long
Transverse No. 8864 Depth "d" 23.885 U.D.

Framing: Table No. _____ Description Bulb angle frame as approved

2nd Longitudinal No. 28934

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 12.274 U.D.

Deck Sheerstrake as approved

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

 100A.1. (Steel)

1 D" (Stl).

Cell D.B. 297' 12705, F.P.T. 1745, A.P.T. 1775

F.K, 5 B.H, cm, Lloyd's A.C.P.

Q 89', B 72', F 25'.

TRUNK IN WELL.



[Signature]

[Signature]
3.6.30



© 2020

Lloyd's Register Foundation

The Certificate of Classification to be endorsed "Cargo battens fitted" and the same notation to be printed in the Register Book.

00391-00398-0180