

Crank shaft, diameter of journals as fitted 14 13.05
Intermediate Shafts, diameter as per Rule 13.4
as fitted

Mid. length thickness 0.15
Thrust shaft, diameter at collars as per Rule 0.15
as fitted

(Received at London Office..... 19..)

No. Place Date Jan 16 1929

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to inspect the manufacture of 4 Superheaters in accordance with an letter 31st ult. for Messrs Alan Coy's N.C 780 Mem Smiths Dock Coy's Yard N: 912

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

T. SUGDEN, LIMITED

180 Fleet Street

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

00591 00598 0184

IS A DONKEY BOILER FITTED?

No.

If so, is a report now forwarded?

PLANS. Are approved plans forwarded herewith for Shafting 31. 10 29 Main Boilers 12. 11 29 Auxiliary Boilers