

Received from Chief Ship Surveyor

Rpt.

No. 27 624

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Depth "d" 23.5 $\frac{1}{2}$

Description

Proportions $\frac{\text{Length}}{\text{Depth}} = \dots\dots\dots 11.1$

F.K. G.B.H. Cem. Llyd ased

© 2020

Lloyd's Register
Foundation

003599-003604-0176

Angle, Bulb Angle, Plate, Tee Bulb or Channel
Angles on upper edge

Poop Deck Stringer Plate, breadth & thickness