

Received from Chief Ship Surveyor

24 FEB 1958

NAME "PAN OCEAN"

REPORT Cal.

No. 17966

Standing Conditions of Class: Subject to No. 4 plate in 3rd below sheer
(s.s. from fwd) being permanently repaired next drydocking.

ACTION is DEFERRED for drydocking(grounding).

Assessment of Class (B) (~~As before~~ or None)

Place of Present Survey: (~~Afloat~~ and in dry dock)

Docking: Examination of damage (subject item).

Recommendation:

SUBMITTED record of 'DS 12,57' be assigned,
subject to No. 4 plate in 3rd below sheer
(s.s. from fwd) being specially examined and dealt
with as necessary next drydocking.

DS 12,57 Subject
Amended.

~~DELETE FROM~~ S.R.L.
Drydocking(grounding).



© 2020
22/1/50.

Lloyd's Register
Foundation

003599-003604-0376

low-
versic
31
amer
ban-
3 10
Said.

The
from

g re-
2 7

33 15

three
SOS
ves-
sling
2 36
had

amer
hted

amer
arry-
ships
d by

g re-
TTT
0-ton
ition
king
(See

amer
that
and
gine-

The
from
of
with
unk.
vows.
te.
d on

The
from
Pan
and
wells.
eamer
water
tween
inside
taken
vessel
while

in position lat.
5 E. 100 miles
a. 150 miles