

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME "TWICKENHAM" REPORT George No. 78028.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey BS and O.F. Conversion When due 5.52

NOTED

It is concluded that all lead pipes have been replaced by steel in the main space bridge line and that the Funnel damper has been removed, but the Surveyor should confirm this.

Yes. Sec. Gls. letter 7 18/11/52

*[Signature]*

17/11/52

© 2020



Lloyd's Register  
Foundation

00305-003610-0118

...renewed, will be used hydraulically to 200 lbs/sq in. ...