

STEAMER "SIREDAL"

M.P. Valve Seat.

CRACK

repaired by welding



SIREAAL

Binn. Rpt. No. 519

L 263 / 310

Nordseewerke Emden
G. m. b. H.

Bildstelle



© 2020

Lloyd's Register
Foundation

003605-003610-0127