

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

F 925

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name

"REGULUS"

Official No. 1156

Port of Registry

Helsingfors

This ship has been under survey at

Lübeck


on the 7th July, 1958 and subsequently 1958 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:-

- 1.) All trimming hatches on tween deck blanked off by welded steel plates.
- 2.) Coaling hatch on casing top blanked off by welded steel plates with stiffeners.
- 3.) Ash shoot (ps) removed. Deck and shell plating blanked off by welded insert plates.
- 4.) New oil tight access hatch for settling tank (ps) on tween deck fitted.



Lolip
T.M.T.
20.10.58

A copy of this Report has been placed on board.



© 2020

003605-003610-0131

Lloyd's Register
Foundation