

Lloyd's Register of Shipping.



430524/525
G 4 V 33
2088

Port of Augsburg
Malmedy Str.8

7th September, 1951

This is to Certify that

Heinrich K. Schneider

the undersigned Surveyor to this Society did at the request of Messrs. Maschinenfabrik Augsburg-Nürnberg AG. of Augsburg attend their Works on the 7th September, 1951 for the purpose of inspecting and testing one seamless S.M.Steel air receivers,

made to the order of Messrs. Scheeps & Installatiebedr. of Ijesselmonde approved plan No 1 M 925 - date of approval 8th February, 1937 and intended for the engine No. 430524/525

The material has been tested as required by the rules, and the scantlings of the air receiver are in accordance with the approved plan.

Each air receiver was, in the presence of the undersigned, tested by hydraulic pressure to 60 kg/cm² ~~the receiver was found satisfactory~~ and found satisfactory.

PARTICULARS.

| RECEIVER NUMBER. | LENGTH. | INTERNAL DIAMETER. | THICKNESS. | TENSILE STRENGTH. | ELONGATION. | BENDS. |
|------------------|-------------------------|-------------------------|-------------------------|---|---|-----------------------------|
| | 500 mm mm | 250 mm mm | 8,5 mm mm | 61,8 kg.p.sq.mm kg.p.sq.mm | 18,0 % % IN 200 mm mm | 180° DEGREES. |
| 10886 | 1820 | 250 | 8,5 | 61,8 Yield point kg.p.sq.mm 40,8 | 18,0 | 180° good |

Identification Mark:—

| | |
|-------------------|---|
| No. 10886/2088 | |
| LLOYD'S TEST. | |
| 60 atm. | ✓ |
| W.P. 30 atm. | ✓ |
| H. K. S. 7. 9. 51 | |



Surveyor to Lloyd's Register.

Fee £ : :

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

003605-003610-0188



© 2020

Lloyd's Register
Foundation