

34354

1 AUG 1957

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIPS NAME "PARKWOOD" REPORT Hpl. No. 19813.
jd.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

The class is subject to defective rivets in way of No.3 hold bilge (s.s.) being examined and dealt with at the next drydocking and to side shell plating, etc.(s.s.f.) being permanently repaired at the Special Survey.

There is an Endorsement of Certificate.

A SPECIAL SURVEY(C) became due 6,57.

The HARTLEPOOL Surveyors report 6,57 this ship examined in drydock, bottom coated and the requirements of a Special Survey (D) complied with.

On account of wear and tear, repairs effected to bottom and side shell plating (p & s), deck bulkhead, inner bottom, floors, frames, etc. and to the deferred items as above.

On account of damage due to various causes, repairs effected to side shell plating (s.s.f.), shell riveting, bulwarkplating and other minor items.

The Surveyors further report new type hatch beams fitted at this time to Nos.1,2 & 3 cargo hatchways in accordance with approved plan.

The thicknesses of shell and deckplating as now ascertained by drilling and reported by the Surveyors are as embodied in the report - see also letter dated 24.7.57 - and are considered satisfactory.

IT IS SUBMITTED notations of "DS 6,57" and "SS. Hpl. 6,57(Dr)" be assigned, without special condition, but with Endorsement of Certificate.

DS 6,57.
SS. Hpl. 6,57(Dr). Without.

ENDORSEMENT OF CERTIFICATE.

Indented shellplating aft and at forecastle (p.s.).

FREEBOARD SURVEYORS TO NOTE THIS REPORT.

1-8-57

© 2021
24.7.57

Lloyd's Register
Foundation

003620-003624-0184