

NADIR.

Lnk 24866


Before this case is confirmed  
IT IS SUBMITTED the surveyor be  
requested to state the reason for the  
renewal of the rivet in the longitudinal  
butt strap of the centre boiler

Office note

+LME 3/53

Letter prof etc

on satisfactory reply.



See

3073 153

© 2020

Lloyd's Register  
Foundation

003625 003630-0221

Now done for Docking Vessel placed in dry dock