

Engineer Surveyor

Received from Chief Engineer Surveyor

Regent- Panther

Rpt.

Aug.

No.

95-088

20328

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to set out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points covered in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

Engine

Oil Engines

4 SCSA

10 G. 29½" - 59½"



Boilers fitted with forced draught

Shaft. If fitted with a continuous liner

If fitted with an outside gland of  
approved type

No main boilers  
Yes  
No

The vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is to be classed + LME 5-37

2 DB 180 lb.

L.Y.  
31/5/32.



© 2020

Lloyd's Register  
Foundation

003640-003648-0061