

Ship Surveyor

Received from Chief Ship Surveyor

ME SH T.S. SLIGO

Rpt. Sub No. 4826

Notes of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/22.

This vessel has left Dublin for Glasgow to have the machinery installed. When submitted the Glasgow surveyor be advised and requested to give the case the necessary attention and to forward a report on form 8 when the survey has been completed.

Concluded the riveting of the hulls of the bridge side plating is as required but the <sup>Dublin</sup> Surveyor should be requested to state if this is so. It should be pointed out to the ~~Surveyor~~ <sup>Surveyor</sup> that the foreboard is not a condition of the class.