


COPY

LLOYD'S REGISTER OF SHIPPING

2302

COPY FOR LONDON



Port Jacksonville, Florida

March 9, 1960

This is to Certify that I have

Surveyed the S.S. "RINCON HILLS" 10635 tons gross of Montreal on February 9, 1960 and subsequent dates whilst vessel was lying on drydock and afloat at Merrill-Stevens D.D. & R. Co., Jacksonville, Fla., for Damage alleged to have been sustained (A) on 8th April 1959 in consequence of vessel striking dock on completion of a passage to Nuevitas, Cuba, (B) on 26th September 1959 in consequence of vessel striking dock at Punta Cardon, Venezuela, and (C) in consequence of encountering heavy weather on 18th November 1959 while on a passage from Three Rivers, Canada to Texas City, Texas, also on 20th December 1959 while on a voyage from Puerto La Cruz to Portland. Also for Docking Survey and Part Special Survey

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will Recommend that she be ~~retained as now classed with fresh record of DS 2-60.~~

Following may, in my opinion, be credited towards Special Survey:

F.P. & A.P. Tanks Examined internally and tested

Fwd. Deep Tanks Examined internally and tested

All Double Bottom Tanks Examined internally and tested

Cofferdams Examined internally and tested

Chain Locker, Anchors and Chain Cables

Harold Moller

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey
BIS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 15M 8-59 PRINTED IN U. S. A.

003659-003670-0050

© 2020
Lloyd's Register
Foundation