

Received from Chief Ship Surveyor

29 OCT 1959

SHIP'S NAME "OLAV BAKKE"

REPORT

Rot.
Got.

No. 48044
25306

VC

Outstanding Conditions of Class:

SUBJECT to rudder post (E.W. and reinforced 11.58) being specially examined at the next drydocking.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix. (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

- (a) Temporary damage repairs.
- (b) Docking; Contact damage repairs as above.

Recommendation:

SUBMITTED record of 'DS 10.59' be assigned as recommended,
SUBJECT as above.

DS. 10.59. SUBJECT.

IN S.R.L. APPENDIX.

Side shell plating in way of
No.3 hold (s.s.) indented.

DELETE FROM S.R.L.
Drydocking (grounding)



© 2020

Lloyd's Register
Foundation

James
23/10/59.