

F.E.

by Chief Ship Surveyor 13.7.15

Received from Chief Ship Surveyor

EL'S NAME

Shells P. Lannon

Rpt.

Abz

No. 11748

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 35.5

Depth "d" 11.66

Framing: Table No. 3 page 9.

Description

Single angle, as approved

Longitudinal No. 4082

Proportions $\frac{\text{Length}}{\text{Depth}} = 8.8$

Deck Sheerstrake . 44 of an inch instead of .34 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A-1. (Steel) "Steam Trawler", as recommended.

∇ 100 A-1. (Steel) "Steam Trawler".

1 Dk.

WB = D.T. 7.125.

BK $7\frac{1}{2}$. 3 BH . cm . Lugs as per.



© 2020

Lloyd's Register Foundation

063671-003678-0097

Spacing

42

42

Angles on ditto, No.

Tie Plates outside Hatchways