

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

47360

B.S.

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name m.s. "REDWIJS II" ex. "BRITISH ENDURANCE" Official No. \_\_\_\_\_

Port of Registry Rotterdam

This ship has been under survey at Rotterdam

on 195 and the following alterations to the conditions of  
assignment of loadlines have now been effected/found:—

The watertight division has been altered by making waterholes in the bulkheads of some  
cargotanks.

The cargotanks of the ship originally 3 x 9 compartments are forming now 4 compartments viz.:

Compartment No.1( tank 1 and 2, port, centre and starboard)

Compartment No.2( tank 3 and 4, " " " " )

Compartment No.3( tank 5 and 6, " " " " )

Compartment No.4( tank 7,8 and 9, " " " " )

Noted  
at  
H.B. 59

SURVEYOR TO LLOYD'S REGISTER

Also reported on Rpt 8

A copy of this Report has been placed on board.

