

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address | Inland: Committee, London, Telex
Address | Overseas: Committee, London, E.C.3

Telephone: RO Yal 9166
Telex No.: 24305

11th March, 1964.

*This was for
Unlanced ship*

C.
DHGK/DET

Dear Sir,

M.S. "MONTERREY"

As the result of a survey held at Veracruz last December by a Surveyor appointed by Lloyd's Agents class has been continued by the Committee subject to wasted shell plate in way of No.3 hold between frames 59/60 (part doubled and cement box 12.63) being specially examined and dealt with as necessary at the next drydocking. Please inform the Owners accordingly.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Principal Surveyor for Spain,
MADRID.



© 2021

Lloyd's Register
Foundation

003681-003697-0161