

1

MW

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME TRAQUAIR REPORT Gls. No. 71660
 (ex Guernsey Queen) FE

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER~~ - SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Periodical Special Survey (C) When due for Reclassification.
Renewal of fore part
Damage

NOTED

Reinstate Class:

LOCAL

3.47 Gmh.

'S.S. Gmh. - 3.47'

Reclassified 3,47

1 Dk

Cell DB 108' 148t, DTa 6' 73t, FPT 60t, APT 10t

FK, 3BH, Lloyd's A & CP

P 53' Q 51' F 17'

Mchy Aft

O.L. 175.8'

Extreme breadth over belting 29.4'

"h"

E.S.D.

"New fore part 3.47"

The Certificate of Classification on
 be endorsed "Cargo buttons not
 fitted" and the same notation so as
 entered in the Register Book

© 2020
 ABM.

Lloyd's Register
 Foundation

003698-003705-0075