

COPY.

*original memo. with
"Saint Mungo"
Sub 5457.*

Recd. 11th Dec. 1937.

LLOYD'S REGISTER OF SHIPPING,
DUBLIN.

LLOYD'S REGISTER
Received
13 DEC 1937
Ansd. 15
LONDON


10th December 1937.

The Owner's representative has requested me to inform you that he would be much obliged if the Committee would agree to the dry docking of this vessel being postponed until January 1938. He stated that his firm are returning the new M.S. "SAINT EUNAN" to the shipbuilders to have the rudder and steering gear examined as complaints have been received by the Owner's that she does not steer satisfactory. It is desired that the "SAINT MUNGO" be kept in service meantime to take up the cargo intended for the M.S. "SAINT EUNAN".

The Secretary,
GLASGOW.

[Handwritten notes and signatures, including "13 DEC 1937" stamp]

[Vertical stamp: "Approved by the Council 12th December 1937"]



© 2020

Lloyd's Register
Foundation

003766-003711-0007

thickness of Intercostal Plate...	20	✓
Angle <i>Single.</i>	6 3 46	✓

Poop Deck, Angle, *[Symbol]*

4 1/2
2
✓
✓
5 1/2

