



D.9532

TS CL
SPS
ed
S.A. S

22 MAY.1962

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME "NIGEAN STAR"

REPORT Pir.

No. 9548

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The ship is subject to set up shell plate D.3 (s.s.a) and internals in way and to indented shell plates G.5 and H.3 (p.s.f) and J.8 (p.s.a) and structure in way being specially examined and dealt with as necessary by the Special Survey.


A SPECIAL SURVEY (C) became due 9,60. Postponement of the Special Survey until 12,61 was approved 24.11.61. The Notation of "Surveys Overdue - 9,60" was subsequently assigned. The ship is now laid up in the Piraeus district.

ACTION ²s DEFERRED for Special Survey.

The PIRAEUS Surveyors report (4,62) ship examined afloat and repairs to heavy weather damage deferred.

In view of this, IT IS SUBMITTED the ship remains Subject as above, and to set in shell plates ^{1st} and 2nd strakes below sheer abreast main mast house and 3rd below sheer in way of No.4 hold, all p.s., being specially examined and dealt with as necessary by the Special Survey, but ACTION continue to be DEFERRED for Special Survey, also pending further information.

SUBJECT.

Lloyd's Register
Foundation

003706-003714-0008

consequent upon the
in as Classed and to