

Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

16th October, 1941.

Dear Sir,

In reply to your letter of the 10th instant in further reference to the Motorship "EMPIRE JET", I have now to state that the Surveyors inform me that no separate starting air receiver is incorporated in the air line, as the starting air for this engine is supplied direct from the Main Engine Air Reservoir.

I am, Dear Sir,
Yours faithfully,

C. K. Miller
Secretary to the
Glasgow Committee.

The Secretary,
WOKINGHAM.



© 2020

Lloyd's Register
Foundation

003706-003711-0171

003706-003711-0170

reboard

H
R8

2.24

H
R8

E



© 2020

Lloyd's Register
Foundation