

5 MAY 1953

SHIP'S NAME "SODALITY" REPORT Hull No. 59230

Outstanding Conditions of Class: Subject to the buckled stem and indented stem and shell plating (p & s) being dealt with by the Special Survey, to the rudder upper stock being renewed by 3,53 and to permanent repairs to bottom shell plating at the Special Survey also to a spare bower anchor being supplied at the earliest opportunity.

ACTION is DEFERRED for completion of Special Survey by 3,53.

Endorsement of Class (B) ~~xxxxxx~~ or None)

Surveys due: SPECIAL SURVEY (C) due 3,52 was commenced Ipswich 2,52. Postponement of completion until 3,53 previously approved

Nature of Present Survey: (Afloat and in dry dock)

Completion of S.S.(C). Permanent repairs to damage (various causes) including subject items as above.

Special Features: A bower anchor and 30 fathoms of cable supplied but no certificates available for verification.

Is Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)

NONE

S.S. to be completed by:

Recommendation:

SUBMITTED the record of docking 3,53 and notation of "ss.Goo.3,53" be assigned as recommended, subject to a bower anchor and 30 fathoms of cable (supplied 3,53) being verified with certificates at the earliest opportunity.

3,53 Goo. ) Subject.  
ss.Goo.3,53 . )



© 2021

28.4.53

Lloyd's Register Foundation

13