

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "Calumet." Report No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry. When due

✱ 100. A. I. (Steel).

2 Dks (Stl.)

Cell DB 378' 1421t, FPT 163t, APT 34t,
FK, YBH, Cem. Lloyds A.S.C.P., P 37, B 188, F 49.
Date of Build 3.23. *awh*



M *awh* *21/3/23.*
It is concluded the tank top is increased in thickness in way of the hatchways as approved, but the Surveyors should be requested to state if this is so. They should also be requested to state whether the length and capacity of the dry tank are included in those given the double bottom under Engines and Boilers, and whether the capacity the double bottom aft is as reported or as in the sister vessels. *awh.*