



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

2/3, Piazza Cavour, Genoa (408)

Telegrams: Surveyors, Genoa

RECEIVED 27th March, 1954

Telephone No. 290-741  
290-742

Reference  
Classn(S)

Dear Sir,

30 MAR 1954

S.S. "LIVERPOOL"

With reference to your letter dated 19th instant, regarding the above Vessel, we beg to inform you as follows.

We confirm that all the requirements of Circular No. 1994 have been complied with and the Vessel is in order.

The steam starboard generator crankshaft has been replaced by a spare one available on board.

No certificate was available and no test marks were noted on the crankshaft.

We confirm that the Port screwshaft is fitted with a jointed liner whereas the starboard screw shaft is fitted with continuous liner.

The joint of the liner of the Port screwshaft has been examined, tested by hammer and found in order.

We regret that this particular has been omitted from our Report.

Yours faithfully,

The Secretary,  
LONDON.

GV:ss

FOR THE SURVEYORS



Lloyd's Register  
Foundation

003720-005726-0044

003720-005726-0046